

Original post set 1820 by Wm. B. Laughlin with witnesses: 6" hornbeam N 22 E 21 links, 12" hickory S 21 W 12 links per Marion County Atlas pg. 8. Survey by Percy Hosbrook 8-8-1851 indicates no stone nor witnesses per Pike Township Legal Survey Book pg. 33. Scherschel 5-1975 called a stone. This corner fell on Rock Island property. When LNG North got the property the entire site was excavated for the building of the terminal and the stone was destroyed. The corner was reset using Fink, Roberts & Petrie surveys #7374 & #88216C. The location was marked and a Harrison was set. SEE SECTION TRAVERSE NOTES FOR MORE DETAILS. Re-tied by Kiste 2-22-99.

## HC731804

REF.	DISTANCE	DESCRIPTION
1.	15.20′	Due N to E Q 13-17-2 Harrison
2.	16.20′	Mag nail w/MCS brass washer W corner post
3.	4.73'	Mag nail w/MCS brass washer S corner post
4,	9,29′	Mag nail w/MCS brass washer S fence post
5.	29.79'	Boat spike W 12' burr oak
6.	53.53′	Boat spike SE 12" walnut
7.	86,38′	Boat spike SE 12" oak